

## **Dimming Compatibility**

Dimmer	Megaman Lamp		
	8W Versofit Fixed Fire Rated Downlight	8W Versofit Tilt Fire Rated Downlight	8W Versofit IP65 Fire Rated Downlight
	519406, 519728, 519607, 519315, 519160, 519170	519317, 519681, 519353, 519715, 519843, 519301	519379, 519085, 519609, 519627, 519384, 519048
HAMILTON LEDSTAT100W	<b>✓</b>	<b>✓</b>	10 lamps
Varilight ZOJP250-P - Version 10+	10 lamps	10 lamps	10 lamps
Varilight JQP401W - Version 10+	10 Igmps	10 lamps	10 lamps
Aurora AU-DSP400x	10 lamps	10 lamps	10 lamps

During operation some combinations of approved dimmers and LED lamps/fittings may exhibit a buzzing sound. This sound may be more pronounced in environments with very low DB levels and thus sound noisier.

Historically this noise may have come from vibrating components in the lamp, transformer and dimmer and the buzzing can still exist, but for different reasons. This could be due to the interaction of components from the circuitry in the dimmer and the lamp &/or driver. Additionally, the supply voltage can induce further noise which electronic circuitry is more sensitive too. Provided the supply voltage is within specification and the tested dimmers are published as compatible by both the lamp/fitting and dimmer manufacturer, the buzzing does not signify a fault or warranty issue with the lamp and will not affect the lamp life.

We strive to manage the noise with continued development and by sharing test data with major dimming and controls manufacturers to help improve and expand on the range of compatible



Dimmer recommended by Megaman, up to number of lamps stated.



Dimmer not recommended by Megaman.

TBC

To Be Confirmed due to tests pending.

Based on testing undertaken by Megaman. Megaman cannot accept responsibility for changes made by dimmer manufacturers. All information stated is correct at time of publication and is subject to change without prior notice. Please visit www.megamanuk.com for latest information.

Last Updated

20/12/2017